

### **ORIGINAL CHAPEL PARKET – GRADING DESCRIPTION**

# 1. PREMIER / 1-BIS

Allowed	Not Allowed	Sample
Knots up to max 15 mm	Sapwood	
Cracks up to max 20 mm	End cracks	
Natural colour differences	Insect damage	
	Centre core	
	Ingrown bark	-77-8
	Grown defects	want -
	Mechanical defects	

#### 2. RUSTIC A

Allowed	Not Allowed	Sample
Knots up to max 40 mm	End cracks	
Cracks up to max 20 mm	Insect damage	Second when the second
Natural colour differences	Centre core	
Sapwood up to max 10 mm	Ingrown bark	and the same of th
	Grown defects	
	Mechanical defects	The second second
	·	

# 3. RUSTIC A/B

Allowed	Not Allowed	Sample
A mixture of approximately 50% Rustic A and 50 % Rustic B		
		West on the second
		And Street
		The second secon
		A STATE OF THE PARTY OF THE PAR
		The second

### 4. RUSTIC B

NOSTIC D				
Not Allowed	Sample			
Insect damage				
Mechanical defects				
Ingrown bark	The state of the s			
	- 12h van -			
	The formal of			
	and antiques			
	Insect damage Mechanical defects			

• Widths > 245 mm are only deliverable in Rustic Mix or Rustic B grading